

Component Procedures: PROM - Programmable Read Only Memory

Table of Contents

1. All Technical Service Bulletins (itype_100)
2. Customer Interest Bulletins (itype_109)
3. Repair Tips (itype_110)
4. Driveability (itype_131)
5. False instrument warning light/gauges (itype_136)
6. Starting problems (itype_171)

Component Procedures: PROM - Programmable Read Only Memory

All Technical Service Bulletins (itype_100)

Tsbs

- Engine Controls - Flash Programming Failure Recovery (18-037-05, 2005/10/20)
- I/M Testing - OBDII CARB Readiness Monitor Information (25-02-98, 1998/10/23)
- PCM - Addition of A Clear Flood Feature (18-37-98, 1998/12/18)
- PCM - Start and Stall, Idle Undershoot/Lost IAC Steps (18-36-98, 1998/12/18)
- PCM - False Mil ON, DTC P0443 Set (18-35-98, 1998/12/18)
- PCM - Idle RPM Undershoot/Overshoot (18-41-98, 1998/12/18)
- PCM - Erroneous Engine Misfire (18-25-99, 1999/11/15)

Customer Interest Bulletins (itype_109)

Tsbs

- I/M Testing - OBDII CARB Readiness Monitor Information (25-02-98, 1998/10/23)
- PCM - Addition of A Clear Flood Feature (18-37-98, 1998/12/18)
- PCM - Start and Stall, Idle Undershoot/Lost IAC Steps (18-36-98, 1998/12/18)
- PCM - False Mil ON, DTC P0443 Set (18-35-98, 1998/12/18)
- PCM - Idle RPM Undershoot/Overshoot (18-41-98, 1998/12/18)
- PCM - Erroneous Engine Misfire (18-25-99, 1999/11/15)

Repair Tips (itype_110)

Tsbs

- Engine Controls - Flash Programming Failure Recovery (18-037-05, 2005/10/20)

Driveability (itype_131)

Tsbs

- PCM - Start and Stall, Idle Undershoot/Lost IAC Steps (18-36-98, 1998/12/18)
- PCM - Idle RPM Undershoot/Overshoot (18-41-98, 1998/12/18)
- PCM - Erroneous Engine Misfire (18-25-99, 1999/11/15)

False instrument warning light/gauges (itype_136)

Tsbs

- PCM - False Mil ON, DTC P0443 Set (18-35-98, 1998/12/18)

Starting problems (itype_171)

Tsbs

- PCM - Addition of A Clear Flood Feature (18-37-98, 1998/12/18)
- PCM - Start and Stall, Idle Undershoot/Lost IAC Steps (18-36-98, 1998/12/18)