

Component Procedures: Interior Moulding / Trim

Table of Contents

1. Coat Hook Replacement (Coupe) (Article 10075)
2. Interior Trim and Paneling - Fastener Specifications (Article 10103)
3. All New Technical Service Bulletins (itype_432)
4. All Technical Service Bulletins (itype_100)
5. Noise (itype_156)
6. Out of specification (itype_158)
7. OEM Policies and Procedures (itype_120)
8. Vehicle / Component Identification (itype_118)
9. Safety (itype_107)

Component Procedures: Interior Moulding / Trim

Coat Hook Replacement (Coupe) (Article 10075)

Callout Component Name

1 Coat Hook Fastener Caution: Refer to Fastener Caution . Procedure Use a small flat-bladed tool to open the integral coat hook cover to access the screw. Tighten 6 Nm (53 lb in)

Procedure

Use a small flat-bladed tool to open the integral coat hook cover to access the screw.

6 Nm (53 lb in)

2 Coat Hook Assembly

Interior Trim and Paneling - Fastener Specifications (Article 10103)

Application Specification

Metric English

Coat Hook Fastener 6 Nm 53 lb in

Front Side Door Trim Panel Fastener 2 Nm 18 lb in

Front Top Stowage Compartment Boot Rear Retaining Post Bolt And Nut 9 Nm 80 lb in

Luggage Shade Fastener 10 Nm 89 lb in

Sunshade Support Fastener 3 Nm 25 lb in

Sunshade Fastener 3 Nm 25 lb in

All New Technical Service Bulletins (itype_432)

Tsbs

- Information on GM Approved Vehicle Interior Cleaning Methods (26-NA-120, 2026/04/13)
- Information on Proper Use of Floor Mats (10-08-110-001M, 2026/01/08)

All Technical Service Bulletins (itype_100)

Tsbs

- Vehicle - Reuse of Fasteners and Proper Torque Info (15-NA-069, 2015/11/30)
- White Film/Residue on Vehicle Interior, Door Trim Panels and/or Instrument Panel (IP) (PI0799A, 2015/10/22)
- Recall - Loss of Air Bag Warning Label Adhesion (13284A, 2013/10/30)
- Information on GM Approved Vehicle Interior Cleaning Methods (26-NA-120, 2026/04/13)
- Hiss Noise Or Gurgle Noise From Dash - Reduced Heater Performance (PIC5984B, 2016/03/18)
- Information on Accessory All-Weather Floor Liners and Flat Mats Warped or Mis-shapen (21-NA-026, 2023/07/17)
- Information on Proper Use of Floor Mats (10-08-110-001M, 2026/01/08)

Noise (itype_156)

Tsbs

- Hiss Noise Or Gurgle Noise From Dash - Reduced Heater Performance (PIC5984B, 2016/03/18)

Out of specification (itype_158)

Tsbs

- White Film/Residue on Vehicle Interior, Door Trim Panels and/or Instrument Panel (IP) (PI0799A, 2015/10/22)

OEM Policies and Procedures (itype_120)

Tsbs

- Information on GM Approved Vehicle Interior Cleaning Methods (26-NA-120, 2026/04/13)
- Information on Proper Use of Floor Mats (10-08-110-001M, 2026/01/08)

Vehicle / Component Identification (itype_118)

Tsbs

- Vehicle - Reuse of Fasteners and Proper Torque Info (15-NA-069, 2015/11/30)

Safety (itype_107)

Tsbs

- Recall - Loss of Air Bag Warning Label Adhesion (13284A, 2013/10/30)