

Component Procedures: Voice Activation System

Table of Contents

1. All New Technical Service Bulletins (itype_432)
2. All Technical Service Bulletins (itype_100)
3. Erratic Operation (itype_132)
4. Poor performance (itype_162)
5. Service Campaigns (itype_108)

Component Procedures: Voice Activation System

All New Technical Service Bulletins (itype_432)

Tsbs

- Diagnostic Tip: Voice Recognition Errors When Using iPhone With One Or More Emojis/Emoticons/Symbols In Contacts List (PIC5953D, 2018/06/14)

All Technical Service Bulletins (itype_100)

Tsbs

- Voice Recognition Release Note for v2017 Map Update (17-NA-058, 2017/03/02)
- Diagnostic Tip-Voice Recognition For Navigation Entry Inaccurate at times (PIC6185A, 2017/09/06)
- Diagnostic Tip: Voice Recognition Errors When Using iPhone With One Or More Emojis/Emoticons/Symbols In Contacts List (PIC5953D, 2018/06/14)
- Campaign - Connected Navigation Voice Command Not Working (12315A, 2013/01/31)

Erratic Operation (itype_132)

Tsbs

- Diagnostic Tip: Voice Recognition Errors When Using iPhone With One Or More Emojis/Emoticons/Symbols In Contacts List (PIC5953D, 2018/06/14)

Poor performance (itype_162)

Tsbs

- Diagnostic Tip-Voice Recognition For Navigation Entry Inaccurate at times (PIC6185A, 2017/09/06)

Service Campaigns (itype_108)

Tsbs

- Campaign - Connected Navigation Voice Command Not Working (12315A, 2013/01/31)