

Component Procedures: Auxiliary Input / Output Jack

Table of Contents

1. Audio Player and USB Receptacle Replacement (Article 10976)
2. All New Technical Service Bulletins (itype_432)
3. All Technical Service Bulletins (itype_100)
4. Repair Tips (itype_110)
5. Erratic Operation (itype_132)
6. Miscellaneous Information (itype_111)

Component Procedures: Auxiliary Input / Output Jack

Audio Player and USB Receptacle Replacement (Article 10976)

Callout Component Name

Preliminary Procedure Open the front floor console armrest. Remove the front floor console rear cover. Refer to Front Floor Console Rear Cover Replacement

Preliminary Procedure

- Open the front floor console armrest.
 - Remove the front floor console rear cover. Refer to Front Floor Console Rear Cover Replacement
- 1 Audio Disc Player and USB Receptacle Procedure Depress the tabs to remove the receptacle. Disconnect the electrical connector.

Procedure

- Depress the tabs to remove the receptacle.
- Disconnect the electrical connector.

All New Technical Service Bulletins (itype_432)

Tsbs

- Diagnostic Tip - Security Light on Intermittently / No Crank/No Start or Start Stall / Keyless Access Vehicles May Display No Remote/Fob Detected / Poor or No RKE Range / Service TPM (PIC5650M, 2025/08/06)

All Technical Service Bulletins (itype_100)

Tsbs

- Diagnostic Tip: Apple Device Connectivity Issues due to USB Cord Concern (PIT5399A, 2018/05/23)
- Diagnostic Tip - Security Light on Intermittently / No Crank/No Start or Start Stall / Keyless Access Vehicles May Display No Remote/Fob Detected / Poor or No RKE Range / Service TPM (PIC5650M, 2025/08/06)
- Audio System - USB/Multimedia Interface Information (09-08-44-013D, 2012/06/26)

Repair Tips (itype_110)

Tsbs

- Audio System - USB/Multimedia Interface Information (09-08-44-013D, 2012/06/26)

Erratic Operation (itype_132)

Tsbs

- Diagnostic Tip: Apple Device Connectivity Issues due to USB Cord Concern (PIT5399A, 2018/05/23)

Miscellaneous Information (itype_111)

Tsbs

- Diagnostic Tip: Apple Device Connectivity Issues due to USB Cord Concern (PIT5399A, 2018/05/23)