

Component Procedures: Relays and Modules - Accessories and Optional Equipment

Table of Contents

1. All New Technical Service Bulletins (itype_432)
2. All Technical Service Bulletins (itype_100)
3. Repair Tips (itype_110)
4. Low, Dead battery (itype_153)
5. Out of specification (itype_158)
6. Poor performance (itype_162)
7. Miscellaneous Information (itype_111)
8. OEM Policies and Procedures (itype_120)
9. Service Campaigns (itype_108)

Component Procedures: Relays and Modules - Accessories and Optional Equipment

All New Technical Service Bulletins (itype_432)

Tsbs

- OnStar Module 2G Sunset Information (23-NA-001, 2025/03/28)

All Technical Service Bulletins (itype_100)

Tsbs

- Vehicle Communication Interface Module (VCIM) Programming Not Completed (17398, 2018/03/09)
- Normal Characteristic - OnStar Power Consumption (PIC4935F, 2017/02/25)
- Programming And Activation Of Replacement OnStar Modules (VCIM) (PIC5588C, 2017/02/06)
- Navigation System - DVD Navigation Update Program (06-08-44-012G, 2013/09/24)
- Missing OnStar® Owner Kit Integration in Vehicle Owner Manual (PI0574A, 2013/05/28)
- Diagnostic Tip: OnStar Vehicles with B101D and Symptom Codes (PIT5236K, 2017/09/29)
- Diagnostic Tip - OnStar Back-up Battery Failure (PIC4541F, 2017/01/11)
- Electrical - Aftermarket Devices May Interfere With OnStar(R) (08-08-46-004A, 2012/11/30)
- OnStar Module 2G Sunset Information (23-NA-001, 2025/03/28)
- OnStar® TBT (Turn by Turn) And Digit Display Location (PIC4510C, 2012/07/18)
- Loss of Radio Audio Shortly After an OnStar In-Vehicle Voice Message Is Heard (20-NA-026, 2020/07/22)
- Diagnostic Tip: Diagnosing Vehicles with OnStar DTC B101D-37 (PIC5492F, 2017/10/05)
- Requirements For OnStar Over The Air Programming And Updates (PIC6107A, 2018/11/20)
- Campaign - Navigation Radio Software Update (12315A, 2013/02/01)
- OnStar(R) - Voice Recognition Operation Issues (PIC3011H, 2014/02/26)

Repair Tips (itype_110)

Tsbs

- Electrical - Aftermarket Devices May Interfere With OnStar(R) (08-08-46-004A, 2012/11/30)
- Navigation System - DVD Navigation Update Program (06-08-44-012G, 2013/09/24)
- OnStar(R) - Voice Recognition Operation Issues (PIC3011H, 2014/02/26)

Low, Dead battery (itype_153)

Tsbs

- Diagnostic Tip - OnStar Back-up Battery Failure (PIC4541F, 2017/01/11)

Out of specification (itype_158)

Tsbs

- Normal Characteristic - OnStar Power Consumption (PIC4935F, 2017/02/25)

Poor performance (itype_162)

Tsbs

- Loss of Radio Audio Shortly After an OnStar In-Vehicle Voice Message Is Heard (20-NA-026, 2020/07/22)

Miscellaneous Information (itype_111)

Tsbs

- Requirements For OnStar Over The Air Programming And Updates (PIC6107A, 2018/11/20)

OEM Policies and Procedures (itype_120)

Tsbs

- Missing OnStar® Owner Kit Integration in Vehicle Owner Manual (PI0574A, 2013/05/28)

Service Campaigns (itype_108)

Tsbs

- Vehicle Communication Interface Module (VCIM) Programming Not Completed (17398, 2018/03/09)
- Campaign - Navigation Radio Software Update (12315A, 2013/02/01)