

Component Procedures: Roof and Associated Components

Table of Contents

1. Parts and Labor (itype_189)
2. All Technical Service Bulletins (itype_100)
3. Customer Interest Bulletins (itype_109)
4. Repair Tips (itype_110)
5. Erratic Operation (itype_132)
6. Inoperative (itype_148)
7. Leaks (itype_149)
8. Loose (itype_150)
9. Noise (itype_156)
10. Out of specification (itype_158)
11. Poor performance (itype_162)
12. OEM Policies and Procedures (itype_120)
13. Vehicle / Component Identification (itype_118)
14. Service Campaigns (itype_108)

Component Procedures: Roof and Associated Components

Parts and Labor (itype_189)

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Remove & Replace	Sunroof > Motor, R&R	B	1.0	0.8
Remove & Replace	Sunroof > Switch, R&R	B	1.3	0.0

All Technical Service Bulletins (itype_100)

Tsbs

- Power Folding Top Diagnostic Tips (PIC5610G, 2016/09/14)
- Water Leak In Rear Floor Area (PIC5458D, 2015/11/10)
- Normal Characteristic - Folding Top Side Rails May Not Stow Completely When Lowering Top (PIC6069, 2017/06/28)
- Convertible Roof Cloth Sags At Rear / Large Gap Between Number 5 Bow And Rear Panel (PIC5449D, 2015/11/04)
- Information On Convertible Roof Rivet Replacement (16-NA-297, 2016/09/13)
- Folding Top Pulls Loose From Rear Side Rail (PIC5605A, 2018/04/16)
- Folding Top Leans to One Side During Top Cycle (16-NA-293, 2016/09/12)
- Sunroof Will Not Open/Close or is Noisy During Operation (PI0176C, 2013/07/17)
- Campaign - Convertible Top Frame Modification (13113, 2013/04/16)
- Performance Of XM Radio System With Sunroof Fully Open (PIC3074F, 2019/02/04)
- Hydraulic Pump Leaking Fluid in Area of Rear Seat, Floor or Trunk, Convertible Top Inoperative or Noise (PI0625A, 2013/04/30)
- General Guidelines for Inspection of Convertible Water Management Bag Anytime Folding Top is Removed (PI0406B, 2015/06/25)
- Information on Sunroof Glass Seal Creak Noise When Contacting Metal Roof Flange (PI0810, 2012/09/12)

Customer Interest Bulletins (itype_109)

Tsbs

- Folding Top Leans to One Side During Top Cycle (16-NA-293, 2016/09/12)

Repair Tips (itype_110)

Tsbs

- Power Folding Top Diagnostic Tips (PIC5610G, 2016/09/14)

Erratic Operation (itype_132)

Tsbs

- Performance Of XM Radio System With Sunroof Fully Open (PIC3074F, 2019/02/04)

Inoperative (itype_148)

Tsbs

- Sunroof Will Not Open/Close or is Noisy During Operation (PI0176C, 2013/07/17)
- Hydraulic Pump Leaking Fluid in Area of Rear Seat, Floor or Trunk, Convertible Top Inoperative or Noise (PI0625A, 2013/04/30)

Leaks (itype_149)

Tsbs

- Water Leak In Rear Floor Area (PIC5458D, 2015/11/10)
- Hydraulic Pump Leaking Fluid in Area of Rear Seat, Floor or Trunk, Convertible Top Inoperative or Noise (PI0625A, 2013/04/30)

Loose (itype_150)

Tsbs

- Folding Top Leans to One Side During Top Cycle (16-NA-293, 2016/09/12)

Noise (itype_156)

Tsbs

- Sunroof Will Not Open/Close or is Noisy During Operation (PI0176C, 2013/07/17)
- Hydraulic Pump Leaking Fluid in Area of Rear Seat, Floor or Trunk, Convertible Top Inoperative or Noise (PI0625A, 2013/04/30)
- Information on Sunroof Glass Seal Creak Noise When Contacting Metal Roof Flange (PI0810, 2012/09/12)

Out of specification (itype_158)

Tsbs

- Convertible Roof Cloth Sags At Rear / Large Gap Between Number 5 Bow And Rear Panel (PIC5449D, 2015/11/04)
- Folding Top Pulls Loose From Rear Side Rail (PIC5605A, 2018/04/16)

Poor performance (itype_162)

Tsbs

- Sunroof Will Not Open/Close or is Noisy During Operation (PI0176C, 2013/07/17)
- Performance Of XM Radio System With Sunroof Fully Open (PIC3074F, 2019/02/04)

OEM Policies and Procedures (itype_120)

Tsbs

- General Guidelines for Inspection of Convertible Water Management Bag Anytime Folding Top is Removed (PI0406B, 2015/06/25)

Vehicle / Component Identification (itype_118)

Tsbs

- Information On Convertible Roof Rivet Replacement (16-NA-297, 2016/09/13)

Service Campaigns (itype_108)

Tsbs

- Campaign - Convertible Top Frame Modification (13113, 2013/04/16)