

Component Procedures: Key

Table of Contents

1. All New Technical Service Bulletins (itype_432)
2. All Technical Service Bulletins (itype_100)
3. Repair Tips (itype_110)
4. Erratic Operation (itype_132)
5. Out of specification (itype_158)
6. Poor performance (itype_162)
7. Miscellaneous Information (itype_111)
8. OEM Policies and Procedures (itype_120)
9. Safety (itype_107)
10. Service Campaigns (itype_108)

Component Procedures: Key

All New Technical Service Bulletins (itype_432)

Tsbs

- Diagnostic Tip - Unable to Learn RKE Transmitters (PIT4945H, 2019/02/19)
- Key Code Security Rules and Information on GM KeyCode Look-Up Application (U.S. Only) (10-00-89-009G, 2025/07/23)

All Technical Service Bulletins (itype_100)

Tsbs

- Key & Transmitter Programming (PIC6401, 2020/02/03)
- Requesting a New Key Code for Customer with Lost or Stolen Keys (12-00-89-002E, 2021/11/17)
- N192223230 — Incorrect Service Ignition Key (N192223230, 2020/01/08)
- Information for Fleet Vehicles - Ignition Key, Fob and Key Rings Configuration (14-00-89-004D, 2017/10/23)
- 14294C – Ignition Key (14294C, 2021/03/23)
- Recall 14V346000: Ignition Key Replacement (NHTSA14V346000, 2014/06/20)
- Diagnostic Tip - Key Does Not Fold Or Will Not Stay Closed (PIC4788G, 2016/06/23)
- Key Cutting Procedure for Obtaining Replacement Key (09-00-89-029L, 2014/04/22)
- Key Code Security Rules and Information on GM KeyCode Look-Up Application (U.S. Only) (10-00-89-009G, 2025/07/23)
- Vehicles with Key Codes Improperly Handled by Third Party (44180-03, 2017/03/23)
- Intermittently Key Will Not Rotate in Door or Ignition Lock Cylinder (PI0091B, 2015/04/28)
- Diagnostic Tip - Unable to Learn RKE Transmitters (PIT4945H, 2019/02/19)
- Locks - Key Code Security Rules, Applications (Canada) (10-00-89-010C, 2013/07/12)

Repair Tips (itype_110)

Tsbs

- Locks - Key Code Security Rules, Applications (Canada) (10-00-89-010C, 2013/07/12)

Erratic Operation (itype_132)

Tsbs

- Diagnostic Tip - Unable to Learn RKE Transmitters (PIT4945H, 2019/02/19)
- Diagnostic Tip - Key Does Not Fold Or Will Not Stay Closed (PIC4788G, 2016/06/23)

Out of specification (itype_158)

Tsbs

- N192223230 — Incorrect Service Ignition Key (N192223230, 2020/01/08)

Poor performance (itype_162)

Tsbs

- Intermittently Key Will Not Rotate in Door or Ignition Lock Cylinder (PI0091B, 2015/04/28)

Miscellaneous Information (itype_111)

Tsbs

- Information for Fleet Vehicles - Ignition Key, Fob and Key Rings Configuration (14-00-89-004D, 2017/10/23)

OEM Policies and Procedures (itype_120)

Tsbs

- Key & Transmitter Programming (PIC6401, 2020/02/03)
- Requesting a New Key Code for Customer with Lost or Stolen Keys (12-00-89-002E, 2021/11/17)
- Key Cutting Procedure for Obtaining Replacement Key (09-00-89-029L, 2014/04/22)
- Key Code Security Rules and Information on GM KeyCode Look-Up Application (U.S. Only) (10-00-89-009G, 2025/07/23)

Safety (itype_107)

Tsbs

- N192223230 — Incorrect Service Ignition Key (N192223230, 2020/01/08)
- 14294C – Ignition Key (14294C, 2021/03/23)

- Recall 14V346000: Ignition Key Replacement (NHTSA14V346000, 2014/06/20)

Service Campaigns (itype_108)

Tsbs

- Vehicles with Key Codes Improperly Handled by Third Party (44180-03, 2017/03/23)