

Component Procedures: Relays and Modules - Accessories and Optional Equipment

Table of Contents

1. All New Technical Service Bulletins (itype_432)
2. All Technical Service Bulletins (itype_100)
3. Software Update Bulletins (itype_434)
4. OEM Policies and Procedures (itype_120)
5. Service Campaigns (itype_108)

Component Procedures: Relays and Modules - Accessories and Optional Equipment

All New Technical Service Bulletins (itype_432)

Tsbs

- AVN PINHOLE RESET FOR BLUELINK SERVICES (SERVICE CAMPAIGN 9C1) (25-01-024H-1, 2025/05/12)

All Technical Service Bulletins (itype_100)

Tsbs

- AVN PINHOLE RESET FOR BLUELINK SERVICES (SERVICE CAMPAIGN 9C1) (25-01-024H-1, 2025/05/12)
- BLUELINK, MULTIMEDIA AND NAVIGATION UPDATE FOR 3G SUNSET (22-GI-008H, 2022/12/14)
- HYUNDAI OVER-THE-AIR (OTA) SOFTWARE UPDATE INTRODUCTION AND CUSTOMER COMMUNICATION INFORMATION (23-GI-012H, 2023/12/19)
- BLIND-SPOT COLLISION WARNING (BCW) MODULE REPLACEMENT INFORMATION (19-BE-008H, 2019/05/01)

Software Update Bulletins (itype_434)

Tsbs

- HYUNDAI OVER-THE-AIR (OTA) SOFTWARE UPDATE INTRODUCTION AND CUSTOMER COMMUNICATION INFORMATION (23-GI-012H, 2023/12/19)

OEM Policies and Procedures (itype_120)

Tsbs

- BLIND-SPOT COLLISION WARNING (BCW) MODULE REPLACEMENT INFORMATION (19-BE-008H, 2019/05/01)

Service Campaigns (itype_108)

Tsbs

- AVN PINHOLE RESET FOR BLUELINK SERVICES (SERVICE CAMPAIGN 9C1) (25-01-024H-1, 2025/05/12)