

Component Procedures: Air Door Actuator / Motor

Table of Contents

1. Parts and Labor (itype_189)
2. Components (itype_32)
3. Blend Door Actuator Replacement (Article 2038844)
4. Defrost Door Actuator Replacement (Article 2036065)
5. Floor Door Actuator Replacement (Article 2036064)
6. Panel/Defrost Door Actuator Replacement (Article 2036066)
7. Recirculation Air Door Actuator Replacement (Article 2036067)
8. Technician Safety Information (itype_15)
9. All Technical Service Bulletins (itype_100)
10. Customer Interest Bulletins (itype_109)
11. Erratic Operation (itype_132)
12. New / Updated Parts (itype_117)



Component Procedures: Air Door Actuator / Motor


Parts and Labor (itype_189)

Labor


Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Replace	Blend Air Door	B	1.1	0.8
Replace	Heat Defroster Door	B	0.4	0.2
Replace	Outside Air Recirculation	B	0.4	0.2
Replace	Panel/Defroster/Demist	B	0.7	0.6

Components (itype_32)









Blend Door Actuator Replacement (Article 2038844)





Defrost Door Actuator Replacement (Article 2036065)





Floor Door Actuator Replacement (Article 2036064)



Panel/Defrost Door Actuator Replacement (Article 2036066)



Recirculation Air Door Actuator Replacement (Article 2036067)



Technician Safety Information (itype_15)

WARNING: ON VEHICLES EQUIPPED WITH AIRBAGS, REFER TO RESTRAINT SYSTEMS / AIRBAG SYSTEMS BEFORE ATTEMPTING A STEERING WHEEL, STEERING COLUMN, OR INSTRUMENT PANEL COMPONENT DIAGNOSIS OR SERVICE. FAILURE TO TAKE THE PROPER PRECAUTIONS COULD RESULT IN ACCIDENTAL AIRBAG DEPLOYMENT AND POSSIBLE PERSONAL INJURY

All Technical Service Bulletins (itype_100)

Tsbs
 - Heater and A/C - Will Not Switch To Panel Mode (24-12-99, 1999/07/02)

Customer Interest Bulletins (itype_109)

Tsbs
 - Heater and A/C - Will Not Switch To Panel Mode (24-12-99, 1999/07/02)

Erratic Operation (itype_132)

Tsbs

- Heater and A/C - Will Not Switch To Panel Mode (24-12-99, 1999/07/02)

New / Updated Parts (itype_117)

Tsbs

- Heater and A/C - Will Not Switch To Panel Mode (24-12-99, 1999/07/02)