

# **Component Procedures: Control Module**

## **Table of Contents**

1. Transmission Control Module (Article 2036485)
2. All Technical Service Bulletins (itype\_100)
3. Customer Interest Bulletins (itype\_109)
4. No shift/Incorrect gear engagement (itype\_154)

## **Component Procedures: Control Module**

### **Transmission Control Module (Article 2036485)**

This vehicle does not have a  
Transmission Control Module

.

Transmission control is accomplished through the  
Engine Control Module

or

Powertrain Control Module

### **All Technical Service Bulletins (itype\_100)**

Tsbs

- TCM - MIL ON/DTC P1763 Set (21-04-00, 2000/06/30)

### **Customer Interest Bulletins (itype\_109)**

Tsbs

- TCM - MIL ON/DTC P1763 Set (21-04-00, 2000/06/30)

### **No shift/Incorrect gear engagement (itype\_154)**

Tsbs

- TCM - MIL ON/DTC P1763 Set (21-04-00, 2000/06/30)