

Component Procedures: Roof and Associated Components

Table of Contents

1. All Technical Service Bulletins (itype_100)
2. Customer Interest Bulletins (itype_109)
3. Abnormal wear/deterioration (itype_122)
4. Warping (itype_178)
5. New / Updated Parts (itype_117)

Component Procedures: Roof and Associated Components

All Technical Service Bulletins (itype_100)

Tsbs

- Soft Top Windows - Foggy or Hazy (23-39-99, 1999/10/01)
- Hardtop - Roof Sags in The Middle (23-18-00, 2000/05/05)
- Body - Soft Top Zipper cleaner (23-005-04, 2004/03/02)

Customer Interest Bulletins (itype_109)

Tsbs

- Soft Top Windows - Foggy or Hazy (23-39-99, 1999/10/01)
- Hardtop - Roof Sags in The Middle (23-18-00, 2000/05/05)

Abnormal wear/deterioration (itype_122)

Tsbs

- Soft Top Windows - Foggy or Hazy (23-39-99, 1999/10/01)

Warping (itype_178)

Tsbs

- Hardtop - Roof Sags in The Middle (23-18-00, 2000/05/05)

New / Updated Parts (itype_117)

Tsbs

- Hardtop - Roof Sags in The Middle (23-18-00, 2000/05/05)
- Body - Soft Top Zipper cleaner (23-005-04, 2004/03/02)