

Component Procedures: Camshaft, Lifters and Push Rods

Table of Contents

1. All Technical Service Bulletins (itype_100)
2. Customer Interest Bulletins (itype_109)
3. Repair Tips (itype_110)
4. Noise (itype_156)
5. Tools and Equipment (itype_113)

Component Procedures: Camshaft, Lifters and Push Rods

All Technical Service Bulletins (itype_100)

Tsbs

- Engine - Camshaft Timing Information (MTIP-07-12-5, 2007/12/01)
- Engine - VVT Noise At Engine Start Up (0101011, 2011/12/21)
- Computers/Controls KAM Memory Clearing After VVT R & R (MTIP-09-01-3, 2009/01/01)

Customer Interest Bulletins (itype_109)

Tsbs

- Engine - VVT Noise At Engine Start Up (0101011, 2011/12/21)

Repair Tips (itype_110)

Tsbs

- Engine - Camshaft Timing Information (MTIP-07-12-5, 2007/12/01)
- Computers/Controls KAM Memory Clearing After VVT R & R (MTIP-09-01-3, 2009/01/01)

Noise (itype_156)

Tsbs

- Engine - VVT Noise At Engine Start Up (0101011, 2011/12/21)

Tools and Equipment (itype_113)

Tsbs

- Engine - Camshaft Timing Information (MTIP-07-12-5, 2007/12/01)