

Component Procedures: Keyless Entry Transmitter

Table of Contents

1. Parts and Labor (itype_189)
2. All Technical Service Bulletins (itype_100)
3. Repair Tips (itype_110)
4. Transmitter ID Code Registration (Article 1360986)

Component Procedures: Keyless Entry Transmitter

Parts and Labor (itype_189)

Parts

Qualifier	Part #	Name	Price	Note
Transmitter > Without Smart ?	BAN6675RY	Transmitter	230.85	
Transmitter > Without Smart ?	BAP5675RY	Transmitter	242.23	
Transmitter > Without Smart ?	BAN6675RY	Transmitter	230.85	
Transmitter > With Smart Key?	GP9C675RYB	Transmitter	232.05	

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Replace	Transmitter, R&R	B	0.3	0.2

All Technical Service Bulletins (itype_100)

Tsbs

- Keyless Entry - Transmitter Battery Replacement Cautions (0904110, 2010/08/30)

Repair Tips (itype_110)

Tsbs

- Keyless Entry - Transmitter Battery Replacement Cautions (0904110, 2010/08/30)

Transmitter ID Code Registration (Article 1360986)

