

# **Component Procedures: A/C Coupler O-ring**

## **Table of Contents**

1. Parts and Labor (itype\_189)

# Component Procedures: A/C Coupler O-ring

## Parts and Labor (itype\_189)

### Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Replace	All	B	1.0	0.7
Replace	One or Two	B	0.4	0.3