

# **Component Procedures: Sensors and Switches - HVAC**

## **Table of Contents**

1. All Technical Service Bulletins (itype\_100)
2. Customer Interest Bulletins (itype\_109)
3. Poor performance (itype\_162)

# **Component Procedures: Sensors and Switches - HVAC**

## **All Technical Service Bulletins (itype\_100)**

Tsbs

- A/C - Stops Cooling After Long Drive When Hot/Humid (0701109, 2009/09/18)
- Instruments - Ambient Temperature Display Incorrectly (0901009, 2009/03/03)

## **Customer Interest Bulletins (itype\_109)**

Tsbs

- A/C - Stops Cooling After Long Drive When Hot/Humid (0701109, 2009/09/18)
- Instruments - Ambient Temperature Display Incorrectly (0901009, 2009/03/03)

## **Poor performance (itype\_162)**

Tsbs

- A/C - Stops Cooling After Long Drive When Hot/Humid (0701109, 2009/09/18)