

Component Procedures: Power Steering

Table of Contents

1. Electronic Power Steering (Article 15068)
2. All Technical Service Bulletins (itype_100)
3. Customer Interest Bulletins (itype_109)
4. Repair Tips (itype_110)
5. Difficult steering (itype_130)
6. Safety (itype_107)

Component Procedures: Power Steering

Electronic Power Steering (Article 15068)

Electronic Power Steering
Page 1 of 1

All Technical Service Bulletins (itype_100)

Tsbs

- Steering - EHPAS Technical Supplement (0600111, 2011/03/18)
- Recall - Loss Of Power Steering Assist (6010H, 2010/09/15)
- Power Steering - High Steering Effort/MIL/DTC C1099 (0600110, 2010/04/09)
- Recall 10V374000: Loss Power Steering Assist (NHTSA10V374000, 2010/08/12)

Customer Interest Bulletins (itype_109)

Tsbs

- Power Steering - High Steering Effort/MIL/DTC C1099 (0600110, 2010/04/09)

Repair Tips (itype_110)

Tsbs

- Steering - EHPAS Technical Supplement (0600111, 2011/03/18)

Difficult steering (itype_130)

Tsbs

- Power Steering - High Steering Effort/MIL/DTC C1099 (0600110, 2010/04/09)

Safety (itype_107)

Tsbs

- Recall - Loss Of Power Steering Assist (6010H, 2010/09/15)
- Recall 10V374000: Loss Power Steering Assist (NHTSA10V374000, 2010/08/12)