

Component Procedures: Steering Wheel

Table of Contents

1. Parts and Labor (itype_189)
2. All Technical Service Bulletins (itype_100)
3. Customer Interest Bulletins (itype_109)
4. Abnormal wear/deterioration (itype_122)
5. Improper Alignment (itype_145)
6. New / Updated Parts (itype_117)

Component Procedures: Steering Wheel

Parts and Labor (itype_189)

Parts

| Qualifier | Part # | Name | Price | Note |
|-------------------------------|------------|-----------------------|---------|------|
| Steering Wheel > Without Lea? | BP4K32980C | 1 - Steering Wheel | 0.00 | |
| Steering Wheel > Without Lea? | BP4L32980C | 1 - Steering Wheel | 384.18 | |
| Steering Wheel > Without Lea? | BS3L32980 | 1 - Steering Wheel | 568.83 | |
| Steering Wheel > With Leathe? | BS3N32980 | 1 - Steering Wheel | 400.81 | |
| Steering Wheel > With Leathe? | BS3N32980 | 1 - Steering Wheel | 400.81 | |
| Steering Wheel > With Leathe? | BS3M32980 | 1 - Steering Wheel | 396.81 | |
| Steering Wheel > With Leathe? | BR9A32980 | 1 - Steering Wheel | 367.44 | |
| Steering Wheel > With Leathe? | BS3G664M0 | 1 - Engagement Switch | 369.64 | |
| Steering Wheel > With Leathe? | BS3G664M0 | 1 - Engagement Switch | 369.64 | |
| Steering Wheel > With Leathe? | B36V32980 | 1 - Steering Wheel | 1333.40 | |

Labor

| Operation | Qualifier Path | Skill | Std Hrs | Wty Hrs |
|-----------|---------------------|-------|---------|---------|
| Replace | Steering Wheel, R&R | B | 0.5 | 0.3 |

All Technical Service Bulletins (itype_100)

Tsbs

- Steering/Suspension - Steering Wheel Off-Center (0200510R, 2011/11/05)
- Interior - Leather Steering Wheel Coming Apart (0600508, 2008/04/04)

Customer Interest Bulletins (itype_109)

Tsbs

- Steering/Suspension - Steering Wheel Off-Center (0200510R, 2011/11/05)
- Interior - Leather Steering Wheel Coming Apart (0600508, 2008/04/04)

Abnormal wear/deterioration (itype_122)

Tsbs

- Interior - Leather Steering Wheel Coming Apart (0600508, 2008/04/04)

Improper Alignment (itype_145)

Tsbs

- Steering/Suspension - Steering Wheel Off-Center (0200510R, 2011/11/05)

New / Updated Parts (itype_117)

Tsbs

- Interior - Leather Steering Wheel Coming Apart (0600508, 2008/04/04)