

Component Procedures: Accessories and Optional Equipment

Table of Contents

1. Parts and Labor (itype_189)
2. All Technical Service Bulletins (itype_100)
3. Customer Interest Bulletins (itype_109)
4. Repair Tips (itype_110)
5. Erratic Operation (itype_132)
6. Inoperative (itype_148)
7. Noise (itype_156)
8. Miscellaneous Information (itype_111)
9. OEM Policies and Procedures (itype_120)
10. Service Campaigns (itype_108)

Component Procedures: Accessories and Optional Equipment

Parts and Labor (itype_189)

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Diagnose/Test	Mazda_diagnosis - Ihf	B	0.8	0.0

All Technical Service Bulletins (itype_100)

Tsbs

- Audio System - Satellite Radio Serial Number Retrieval (MTIP-08-12-3, 2008/12/01)
- Navigation System - Display Standard For Failed Pixels (0908109, 2009/12/21)
- Audio System - Speaker Noise When Using Auxiliary Device (0903009, 2009/06/24)
- Campaign - Audio Preset Reset Method (ONP03, 2008/12/23)
- Keyless Entry - Transmitter Battery Replacement Cautions (0904110, 2010/08/30)
- Instruments - Info. Display Full Afetr Remote Start (MTIP-09-01-4, 2009/01/01)
- AUDIO / INFOTAINMENT SYSTEM SERVICE INFORMATION (09-004/19, 2019/01/10)
- Audio System - Satellite Presets Erased/Can't Be reset (0900909, 2009/02/16)
- Audio System - iPod(R) Adapter Application Table (MTIP-09-01-8, 2009/01/01)
- Audio System - Irregular Bass Operation (0901408, 2008/05/08)
- Navigation System - Displays Incorrect Map or No Map (0900308, 2008/01/16)
- Navigation System - Beep Sound From Dash While Driving (MTIP-08-12-6, 2008/12/01)
- SIRIUSXM SATELLITE RADIO REGISTRATION TRANSFER AFTER UNIT REPLACEMENT (09-001/19, 2019/01/04)
- Audio System - Sirius Satellite Radio(R) Activation (0901708, 2008/06/17)

Customer Interest Bulletins (itype_109)

Tsbs

- Audio System - Satellite Presets Erased/Can't Be reset (0900909, 2009/02/16)
- Audio System - Speaker Noise When Using Auxiliary Device (0903009, 2009/06/24)
- Audio System - Irregular Bass Operation (0901408, 2008/05/08)
- Navigation System - Displays Incorrect Map or No Map (0900308, 2008/01/16)

Repair Tips (itype_110)

Tsbs

- Audio System - Satellite Radio Serial Number Retrieval (MTIP-08-12-3, 2008/12/01)
- Audio System - iPod(R) Adapter Application Table (MTIP-09-01-8, 2009/01/01)
- Navigation System - Display Standard For Failed Pixels (0908109, 2009/12/21)
- Navigation System - Beep Sound From Dash While Driving (MTIP-08-12-6, 2008/12/01)
- Keyless Entry - Transmitter Battery Replacement Cautions (0904110, 2010/08/30)
- Audio System - Sirius Satellite Radio(R) Activation (0901708, 2008/06/17)
- Instruments - Info. Display Full Afetr Remote Start (MTIP-09-01-4, 2009/01/01)

Erratic Operation (itype_132)

Tsbs

- Audio System - Satellite Presets Erased/Can't Be reset (0900909, 2009/02/16)
- Audio System - Irregular Bass Operation (0901408, 2008/05/08)

Inoperative (itype_148)

Tsbs

- Audio System - Satellite Presets Erased/Can't Be reset (0900909, 2009/02/16)

Noise (itype_156)

Tsbs

- Audio System - Speaker Noise When Using Auxiliary Device (0903009, 2009/06/24)

Miscellaneous Information (itype_111)

Tsbs

- AUDIO / INFOTAINMENT SYSTEM SERVICE INFORMATION (09-004/19, 2019/01/10)

OEM Policies and Procedures (itype_120)

Tsbs

- SIRIUSXM SATELLITE RADIO REGISTRATION TRANSFER AFTER UNIT REPLACEMENT (09-001/19, 2019/01/04)

Service Campaigns (itype_108)

Tsbs

- Campaign - Audio Preset Reset Method (ONP03, 2008/12/23)