

# **Component Procedures: Front Door Window Motor**

## **Table of Contents**

1. Parts and Labor (itype\_189)
2. Removal and Replacement (itype\_401)
3. All Technical Service Bulletins (itype\_100)
4. Customer Interest Bulletins (itype\_109)
5. Component Tests and General Diagnostics (itype\_383)
6. Noise (itype\_156)

# Component Procedures: Front Door Window Motor

## Parts and Labor (itype\_189)


### Parts

| Qualifier            | Part #     | Name         | Price  | Note |
|----------------------|------------|--------------|--------|------|
| Window Motor > Right | GJ6A5858XC | Window Motor | 254.39 |      |
| Window Motor > Left  | G22C5958XC | Window Motor | 269.81 |      |

### Labor

| Operation | Qualifier Path | Skill | Std Hrs | Wty Hrs |
|-----------|----------------|-------|---------|---------|
| Replace   | One Side       | B     | 0.5     | 0.3     |

## Removal and Replacement (itype\_401)



B3E0912W104

## All Technical Service Bulletins (itype\_100)

Tsbs

- Body - Front Door Power Window Motor Noise (0907809, 2009/12/03)


## Customer Interest Bulletins (itype\_109)

Tsbs

- Body - Front Door Power Window Motor Noise (0907809, 2009/12/03)

## Component Tests and General Diagnostics (itype\_383)

| Operation | Terminal            |                     |
|-----------|---------------------|---------------------|
|           | Front: F<br>Rear: E | Front: E<br>Rear: F |
| Open      | GND                 | B+                  |
| Closed    | B+                  | GND                 |



c3u0912w102

## **Noise (itype\_156)**

Tsbs

- Body - Front Door Power Window Motor Noise (0907809, 2009/12/03)