

Component Procedures: Antenna

Table of Contents

1. Parts and Labor (itype_189)
2. Wireless Communication Interface Antenna Replacement (Article 10999)
3. Radio Antenna Base Replacement (Convertible) (Article 10986)
4. Radio Antenna Base Replacement (Coupe) (Article 10987)
5. Radio Antenna Module Replacement (Coupe) (Article 10989)
6. All Technical Service Bulletins (itype_100)
7. Tools and Equipment (itype_113)

Component Procedures: Antenna

Parts and Labor (itype_189)

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Remove & Replace	Antenna & Radio > Antenna, R&R > Convertible	B	0.9	0.0
Remove & Replace	Antenna & Radio > Antenna, R&R > Coupe	B	1.2	0.0
Remove & Replace	Antenna & Radio > Module, R&R	B	1.3	0.0

Wireless Communication Interface Antenna Replacement (Article 10999)

Callout Component Name

Preliminary Procedure Remove the instrument panel assembly. Refer to Instrument Panel Assembly Replacement Preliminary Procedure

Remove the instrument panel assembly. Refer to Instrument Panel Assembly Replacement

1 Wireless Communication Interface Antenna Bluetooth Module Procedure Unsnap the antenna from communication module.

Procedure

Unsnap the antenna from communication module.

Radio Antenna Base Replacement (Convertible) (Article 10986)

Callout Component Name

Preliminary Procedure Remove the rear compartment lid finish panel. Refer to Rear Compartment Lid Carpet Replacement .

Preliminary Procedure

Remove the rear compartment lid finish panel. Refer to Rear Compartment Lid Carpet Replacement .

1 Radio Antenna Base Caution: Refer to Fastener Caution . Procedure Remove the integral bolt and retainer. Disconnect the electrical connections. Disconnect the antenna cable s. Feed the wiring and cable up through the hole in the rear compartment lid panel. Tighten 9 Nm (80 lb in)

Procedure

- Remove the integral bolt and retainer.
 - Disconnect the electrical connections.
 - Disconnect the antenna cable s.
 - Feed the wiring and cable up through the hole in the rear compartment lid panel.
- 9 Nm (80 lb in)

Radio Antenna Base Replacement (Coupe) (Article 10987)

Callout Component Name

Preliminary Procedure Lower the headliner trim panel to access the antenna base fastener. Refer to Headlining Trim Panel Replacement or the sunroof panel trim panel, if equipped. Refer to Sunroof Panel Trim Panel Replacement .

Preliminary Procedure

Lower the headliner trim panel to access the antenna base fastener. Refer to Headlining Trim Panel Replacement or the sunroof panel trim panel, if equipped. Refer to Sunroof Panel Trim Panel Replacement .

1 Radio Antenna Base Caution: Refer to Fastener Caution . Procedure Loosen the integral nut. Disconnect the electrical connections. Disconnect the antenna cable s. Feed the wiring and cable up through the hole in the roof panel. Tighten 10 Nm (89 lb in)

Procedure

- Loosen the integral nut.
 - Disconnect the electrical connections.
 - Disconnect the antenna cable s.
 - Feed the wiring and cable up through the hole in the roof panel.
- 10 Nm (89 lb in)

Radio Antenna Module Replacement (Coupe) (Article 10989)

Callout Component Name

Preliminary Procedure Lower the rear of the headliner trim panel to access the antenna amplifier. Refer to Headlining Trim Panel Replacement or the sunroof panel trim panel, if equipped. Refer to Sunroof Panel Trim

Panel Replacement

Preliminary Procedure

Lower the rear of the headliner trim panel to access the antenna amplifier. Refer to Headlining Trim Panel Replacement or the sunroof panel trim panel, if equipped. Refer to Sunroof Panel Trim Panel Replacement

1 Radio Antenna Module Bolt Caution: Refer to Fastener Caution . Tighten 9 Nm (80 lb in)

9 Nm (80 lb in)

2 Radio Antenna Module Assembly Procedure Disconnect the electrical connection. Disconnect the antenna cable from the rear glass.

Procedure

- Disconnect the electrical connection.
- Disconnect the antenna cable from the rear glass.

All Technical Service Bulletins (itype_100)

Tsbs

- Information on Antenna COAX Repair Kit Availability (17-NA-346, 2019/01/29)

Tools and Equipment (itype_113)

Tsbs

- Information on Antenna COAX Repair Kit Availability (17-NA-346, 2019/01/29)