

Component Procedures: Marker Lamp

Table of Contents

1. Front Side Marker Lamp Replacement (Article 10396)
2. Rear Side Marker Lamp Replacement (Article 10414)

Component Procedures: Marker Lamp

Front Side Marker Lamp Replacement (Article 10396)

Callout Component Name

Preliminary Procedures Remove the front wheelhouse front liner. Refer to Front Wheelhouse Liner Replacement . Insert a small flat-bladed tool into the front bumper fascia lower reinforcement in order to access the locking tab on the front marker lamp . Gently push the locking tab inward in order to release lamp from the bumper fascia assembly. Pull the front marker lamp outward from the front bumper fascia.

Preliminary Procedures

- Remove the front wheelhouse front liner. Refer to Front Wheelhouse Liner Replacement .
- Insert a small flat-bladed tool into the front bumper fascia lower reinforcement in order to access the locking tab on the front marker lamp .
- Gently push the locking tab inward in order to release lamp from the bumper fascia assembly.
- Pull the front marker lamp outward from the front bumper fascia.

1 Front Side Marker Lamp Assembly Tip: Disconnect the electrical connector socket after the lamp has been removed from the front bumper fascia.

Rear Side Marker Lamp Replacement (Article 10414)

Callout Component Name

Preliminary Procedure Remove the rear wheelhouse liner. Refer to Rear Wheelhouse Liner Replacement .

Preliminary Procedure

Remove the rear wheelhouse liner. Refer to Rear Wheelhouse Liner Replacement .

1 Rear Side Marker Lamp Procedure Depress the forward locking tab rearward on the lamp assembly. Rotate the forward edge outward from the rear bumper fascia. Pull the lamp slightly forward to release the tab.

Disconnect the rear side marker lamp socket from the rear side marker lamp assembly.

Procedure

- Depress the forward locking tab rearward on the lamp assembly.
- Rotate the forward edge outward from the rear bumper fascia.
- Pull the lamp slightly forward to release the tab.
- Disconnect the rear side marker lamp socket from the rear side marker lamp assembly.