

Component Procedures: Emergency Contact Button

Table of Contents

1. All Technical Service Bulletins (itype_100)
2. Repair Tips (itype_110)
3. Erratic Operation (itype_132)
4. Low, Dead battery (itype_153)

Component Procedures: Emergency Contact Button

All Technical Service Bulletins (itype_100)

Tsbs

- OnStar- Unwanted Or Phantom Phone Calls (PIC3278G, 2017/02/20)
- Dead Battery After Exiting The Vehicle While On A Bluetooth Cal (PIC6198A, 2016/08/02)

Repair Tips (itype_110)

Tsbs

- Dead Battery After Exiting The Vehicle While On A Bluetooth Cal (PIC6198A, 2016/08/02)

Erratic Operation (itype_132)

Tsbs

- OnStar- Unwanted Or Phantom Phone Calls (PIC3278G, 2017/02/20)

Low, Dead battery (itype_153)

Tsbs

- Dead Battery After Exiting The Vehicle While On A Bluetooth Cal (PIC6198A, 2016/08/02)