

# **Component Procedures: Sensors and Switches - Brakes and Traction Control**

## **Table of Contents**

1. All New Technical Service Bulletins (itype\_432)
2. All Technical Service Bulletins (itype\_100)
3. Customer Interest Bulletins (itype\_109)
4. Repair Tips (itype\_110)
5. Noise (itype\_156)

# **Component Procedures: Sensors and Switches - Brakes and Traction Control**

## **All New Technical Service Bulletins (itype\_432)**

Tsbs

- Multiple U-code Diagnostic Information – With one having symptom Byte 71 (PIT5569C, 2024/09/06)

## **All Technical Service Bulletins (itype\_100)**

Tsbs

- ABS/TCS - DTC's C0710 SYM71 (PIT5076D, 2014/02/10)
- Multiple U-code Diagnostic Information – With one having symptom Byte 71 (PIT5569C, 2024/09/06)
- Ratchet Click or Grind Noise From Front of Vehicle Slow Speeds (16-NA-298, 2016/09/13)

## **Customer Interest Bulletins (itype\_109)**

Tsbs

- Ratchet Click or Grind Noise From Front of Vehicle Slow Speeds (16-NA-298, 2016/09/13)

## **Repair Tips (itype\_110)**

Tsbs

- ABS/TCS - DTC's C0710 SYM71 (PIT5076D, 2014/02/10)

## **Noise (itype\_156)**

Tsbs

- Ratchet Click or Grind Noise From Front of Vehicle Slow Speeds (16-NA-298, 2016/09/13)