

Component Procedures: Power Steering

Table of Contents

1. Specifications Quick Reference (itype_439)
2. Electronic Power Steering (Article 10967)
3. All Technical Service Bulletins (itype_100)
4. Customer Interest Bulletins (itype_109)
5. Leaks (itype_149)
6. Noise (itype_156)

Component Procedures: Power Steering

Specifications Quick Reference (itype_439)

Quick Specifications
- item

Electronic Power Steering (Article 10967)

Electronic Power Steering
Page 1 of 1

All Technical Service Bulletins (itype_100)

Tsbs

- Steering - Power Steering Fluid Leaks (07-02-32-002N, 2013/09/18)
- Power Steering Fluid Leak at Fluid Reservoir or Reservoir Connection (PI0671A, 2017/03/17)
- Power Steering Noise or Fluid Leak from Power Steering Pump, Gear or High Pressure Hose During Extreme Low Temperature Operation (Replace Power Steering Fluid) (12-02-32-002B, 2020/06/05)

Customer Interest Bulletins (itype_109)

Tsbs

- Steering - Power Steering Fluid Leaks (07-02-32-002N, 2013/09/18)

Leaks (itype_149)

Tsbs

- Steering - Power Steering Fluid Leaks (07-02-32-002N, 2013/09/18)
- Power Steering Fluid Leak at Fluid Reservoir or Reservoir Connection (PI0671A, 2017/03/17)
- Power Steering Noise or Fluid Leak from Power Steering Pump, Gear or High Pressure Hose During Extreme Low Temperature Operation (Replace Power Steering Fluid) (12-02-32-002B, 2020/06/05)

Noise (itype_156)

Tsbs

- Power Steering Noise or Fluid Leak from Power Steering Pump, Gear or High Pressure Hose During Extreme Low Temperature Operation (Replace Power Steering Fluid) (12-02-32-002B, 2020/06/05)