

# **Component Procedures: Wiring Harness**

## **Table of Contents**

1. Harness Routing Views (Article 13020)
2. All New Technical Service Bulletins (itype\_432)
3. All Technical Service Bulletins (itype\_100)
4. Customer Interest Bulletins (itype\_109)
5. Repair Tips (itype\_110)
6. Erratic Operation (itype\_132)
7. Inoperative (itype\_148)
8. OEM Policies and Procedures (itype\_120)

# Component Procedures: Wiring Harness

## Harness Routing Views (Article 13020)

- Figure 1: Fog Lamp Harness Routing
- Figure 2: Forward Lamp Harness Routing - Left
- Figure 3: Forward Lamp Harness Routing - Right
- Figure 4: Engine Harness Routing - Left Rear (LFX)
- Figure 5: Engine Harness Routing - Left Rear (L99 or LS3)
- Figure 6: Engine Harness Routing - Right Side (LFX)
- Figure 7: Engine Harness Routing - Right Side (L99 or LS3)
- Figure 8: Engine Harness Routing - Right Side (LSA)
- Figure 9: Transmission Harness Routing - Right Rear (MYB)
- Figure 10: Transmission Harness Routing - Right Rear (MYC)
- Figure 11: Instrument Panel Harness Routing - Left Back Side of the Instrument Panel
- Figure 12: Instrument Panel Harness Routing - Right Back Side of the Instrument Panel (Convertible)
- Figure 13: Instrument Panel Harness Routing - Top Left Overhead
- Figure 14: Instrument Panel Harness Routing - Top Right Overhead
- Figure 15: Roof Console Harness Routing - Top of Windshield (Convertible)
- Figure 16: Door Harness Routing
- Figure 17: Body Harness Routing - Left Front of the Passenger Compartment
- Figure 18: Body Harness Routing - Left Passenger and Rear Compartment
- Figure 19: Body Harness Routing - Right Front of the Passenger Compartment
- Figure 20: Body Harness Routing - Right Passenger Compartment
- Figure 21: Body Harness Routing - Right Rear of the Passenger Compartment (Convertible)
- Figure 22: Body Harness Routing - Right Rear of the Passenger Compartment (Coupe)
- Figure 23: Body Harness Routing - Right Rear Underbody
- Figure 24: Body Harness Routing - Right Rear Compartment (Convertible)
- Figure 25: Body Harness Routing - Luggage Compartment (Convertible)
- Figure 26: Fuel Tank Harness Routing
- Figure 27: Rear Fascia Harness Routing

## All New Technical Service Bulletins (itype\_432)

Tsbs

- Information on Reflective High Temperature Heat and/or Insulating Tape for Wiring Harness Repairs (25-NA-087, 2025/04/03)

## All Technical Service Bulletins (itype\_100)

Tsbs

- Lighting - Door/IP Accent Lighting Inop/Loses Intensity (09-08-42-005E, 2015/02/13)
- Intermittent Malfunction Indicator Lamp (MIL) Illuminated, DTC P2138 with Reduced Engine Power (07-06-04-019G, 2021/12/08)
- Information on Reflective High Temperature Heat and/or Insulating Tape for Wiring Harness Repairs (25-NA-087, 2025/04/03)
- Tire Monitor System - TPMS Lamp On, No Tire Pressures Displayed (PI1241, 2014/05/16)
- Engine Controls - P00C6, P228C Diagnostic Assistance (PIP5209A, 2014/08/18)

## Customer Interest Bulletins (itype\_109)

Tsbs

- Lighting - Door/IP Accent Lighting Inop/Loses Intensity (09-08-42-005E, 2015/02/13)

## Repair Tips (itype\_110)

Tsbs

- Tire Monitor System - TPMS Lamp On, No Tire Pressures Displayed (PI1241, 2014/05/16)
- Engine Controls - P00C6, P228C Diagnostic Assistance (PIP5209A, 2014/08/18)

## Erratic Operation (itype\_132)

Tsbs

- Lighting - Door/IP Accent Lighting Inop/Loses Intensity (09-08-42-005E, 2015/02/13)

## **Inoperative (itype\_148)**

Tsbs

- Lighting - Door/IP Accent Lighting Inop/Loses Intensity (09-08-42-005E, 2015/02/13)

## **OEM Policies and Procedures (itype\_120)**

Tsbs

- Information on Reflective High Temperature Heat and/or Insulating Tape for Wiring Harness Repairs  
(25-NA-087, 2025/04/03)