

Component Procedures: Relays and Modules - Computers and Control Systems

Table of Contents

1. All New Technical Service Bulletins (itype_432)
2. All Technical Service Bulletins (itype_100)
3. Customer Interest Bulletins (itype_109)
4. Repair Tips (itype_110)
5. New / Updated Parts (itype_117)

Component Procedures: Relays and Modules - Computers and Control Systems

All New Technical Service Bulletins (itype_432)

Tsbs

- Identifying Non-GM (Aftermarket) Engine Calibrations for Gasoline Engines Using Tech 2® or GDS 2 (U.S., Canada, Australia, and New Zealand) (09-06-04-026Z, 2025/01/09)

All Technical Service Bulletins (itype_100)

Tsbs

- Engine Controls - Vehicle Stalls When Turning, No DTC's (15-06-04-003, 2015/07/31)
- Engine Controls - MIL ON, DTC's P0300/P0303 Set (PI1122B, 2014/02/10)
- IPC Odometer Programming Method Quick Reference Guide (07-08-49-020R, 2023/09/21)
- Identifying Non-GM (Aftermarket) Engine Calibrations for Gasoline Engines Using Tech 2® or GDS 2 (U.S. and Canada) (09-06-04-026X, 2023/07/31)
- Engine - THIS BULLETIN HAS BEEN CANCELED (04-06-04-054E, 2012/08/06)
- Engine Controls - P00C6, P228C Diagnostic Assistance (PIP5209A, 2014/08/18)
- Identifying Non-GM (Aftermarket) Engine Calibrations for Gasoline Engines Using Tech 2® or GDS 2 (U.S., Canada, Australia, and New Zealand) (09-06-04-026Z, 2025/01/09)
- Engine Controls - Single Cylinder Misfire Diagnostics (PIP5062C, 2014/05/02)

Customer Interest Bulletins (itype_109)

Tsbs

- Engine Controls - Vehicle Stalls When Turning, No DTC's (15-06-04-003, 2015/07/31)

Repair Tips (itype_110)

Tsbs

- Engine Controls - MIL ON, DTC's P0300/P0303 Set (PI1122B, 2014/02/10)
- Engine Controls - P00C6, P228C Diagnostic Assistance (PIP5209A, 2014/08/18)
- Engine Controls - Single Cylinder Misfire Diagnostics (PIP5062C, 2014/05/02)

New / Updated Parts (itype_117)

Tsbs

- Engine - THIS BULLETIN HAS BEEN CANCELED (04-06-04-054E, 2012/08/06)