

Component Procedures: Relays and Modules - Body and Frame

Table of Contents

1. All Technical Service Bulletins (itype_100)
2. Repair Tips (itype_110)
3. Leaks (itype_149)

Component Procedures: Relays and Modules - Body and Frame

All Technical Service Bulletins (itype_100)

Tsbs

- Interior - Heated Seats Inoperative, DTC U0209 Set (PIC5954, 2014/02/06)
- Hydraulic Pump Leaking Fluid in Area of Rear Seat, Floor or Trunk, Convertible Top Inoperative or Noise (PI0625A, 2013/04/30)

Repair Tips (itype_110)

Tsbs

- Interior - Heated Seats Inoperative, DTC U0209 Set (PIC5954, 2014/02/06)

Leaks (itype_149)

Tsbs

- Hydraulic Pump Leaking Fluid in Area of Rear Seat, Floor or Trunk, Convertible Top Inoperative or Noise (PI0625A, 2013/04/30)