

Component Procedures: Trunk / Liftgate Shock / Support

Table of Contents

1. Parts and Labor (itype_189)
2. Rear Compartment Lid Strut Replacement (Article 10132)

Component Procedures: Trunk / Liftgate Shock / Support

Parts and Labor (itype_189)

Parts

Qualifier	Part #	Name	Price	Note
Lift Cylinder > Coupe > With?	92235152	Lift Cylinder	26.86	
Lift Cylinder > Coupe > With?	92235151	Lift Cylinder	27.14	
Lift Cylinder > Convertible	92235153	Lift Cylinder	0.00	

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Remove & Replace	Trunk > Lift Cylinder, R&R > One	C	0.2	0.2
Remove & Replace	Trunk > Lift Cylinder, R&R > Both	C	0.3	0.2

Rear Compartment Lid Strut Replacement (Article 10132)

Callout Component Name

1 Rear Compartment Lid Strut Warning: When a hood hold open device is being removed or installed, provide alternate support to avoid the possibility of damage to the vehicle or personal injury. Caution: Apply pressure only at the end of the liftgate /hood assist rod that you are removing or attaching. Do NOT apply pressure to the middle of the rod because damage or bending will result. Procedure Release the locking retainers on the strut. Ensure the retainers are fully seated when the retainers are reinstalled. If the retainers cannot be fully seated, a new strut should be installed.

Procedure

- Release the locking retainers on the strut.
- Ensure the retainers are fully seated when the retainers are reinstalled. If the retainers cannot be fully seated, a new strut should be installed.