

# **Component Procedures: Rear Bumper**

## **Table of Contents**

1. Quarter Outer Panel Pressure Relief Valve Replacement (Article 10080)
2. All Technical Service Bulletins (itype\_100)
3. Safety (itype\_107)

## **Component Procedures: Rear Bumper**

### **Quarter Outer Panel Pressure Relief Valve Replacement (Article 10080)**

Callout Component Name

Preliminary Procedures Remove the rear bumper fascia . Refer to Rear Bumper Fascia Replacement . Reposition any wiring to gain access to pressure relief valve.

Preliminary Procedures

- Remove the rear bumper fascia . Refer to Rear Bumper Fascia Replacement .
- Reposition any wiring to gain access to pressure relief valve.

1 Pressure Relief Valve

### **All Technical Service Bulletins (itype\_100)**

Tsbs

- Campaign - Rear Bumper Facia Is Melting From License Plate Lamp (15030, 2015/09/21)

### **Safety (itype\_107)**

Tsbs

- Campaign - Rear Bumper Facia Is Melting From License Plate Lamp (15030, 2015/09/21)