

Component Procedures: Convertible Top Moulding / Trim

Table of Contents

1. Folding Top Number 1 Bow Garnish Molding Replacement (Article 13130)
2. Folding Top Side Rail Garnish Molding Replacement (Article 13144)

Component Procedures: Convertible Top Moulding / Trim

Folding Top Number 1 Bow Garnish Molding Replacement (Article 13130)

Callout Component Name

Caution: Always put an automatic transmission in P (Park) or a manual transmission in N (Neutral) and set the park brake before raising or lowering the convertible top . If you raise or lower the convertible top while the vehicle is in motion, you could damage the top or the top mechanism. Caution: Always verify that no objects are in the storage area before lowering the convertible top. Lowering the convertible top when there are objects in the storage area could damage it or break the glass rear window. Caution: The positioning of the latches and linkage rods is factory set to allow safe and proper operation of the system. The adjustment is only to be utilized by the manufacturer of the folding top number 1 bow assembly (not repairing technicians). Attempting adjustment may cause the top to not properly latch causing damage to the top or vehicle. Preliminary Procedure Do not remove the number 1 bow, lay the folding top cover back exposing the four screws to remove the garnish molding. Refer to Folding Top Number 1 Bow Replacement .

Preliminary Procedure

Do not remove the number 1 bow, lay the folding top cover back exposing the four screws to remove the garnish molding. Refer to Folding Top Number 1 Bow Replacement .

1 Folding Top Number 1 Bow Garnish Molding Screw Caution: Refer to Fastener Caution . Procedure Remove the assist handle center bezel by pushing upward in the center. Remove the bezel exposing the screw in the center for the garnish molding. Tighten 2 Nm (18 lb in)

Procedure

Remove the assist handle center bezel by pushing upward in the center. Remove the bezel exposing the screw in the center for the garnish molding.

2 Nm (18 lb in)

2 Folding Top Number 1 Bow Garnish Molding Screw (Qty :4) Tighten 8 Nm (71 lb in)

8 Nm (71 lb in)

3 Folding Top Number 1 Bow Garnish Molding

Folding Top Side Rail Garnish Molding Replacement (Article 13144)

Callout Component Name

Caution: Always verify that no objects are in the storage area before lowering the convertible top . Lowering the convertible top when there are objects in the storage area could damage it or break the glass rear window. Caution: Dry off the convertible top before lowering it. Lowering the convertible top if it is damp, wet, or dirty can cause stains, mildew, and damage to the inside of the vehicle. Preliminary Procedure Open the folding top to the halfway position.

Preliminary Procedure

Open the folding top to the halfway position.

1 Front Top Side Garnish Molding (Qty: 2)

2 Front Top Side Garnish Molding Screws (Qty: 3) Caution: Refer to Fastener Caution . Tighten 8 Nm (71 lb in)

8 Nm (71 lb in)

3 Front Top Side Garnish Molding Clip

4 Front Top Side Garnish Molding Spring

5 Front Top Side Garnish Molding