

# **Component Procedures: Antenna, Radio**

## **Table of Contents**

1. Parts and Labor (itype\_189)
2. Radio Antenna Coil Replacement (Article 10988)

# Component Procedures: Antenna, Radio

## Parts and Labor (itype\_189)

### Parts

Qualifier	Part #	Name	Price	Note
Antenna > Without Digital Au?	92200775	Antenna	0.00	
Antenna > With Digital Audio	92239705	Antenna	0.00	
Antenna > With Digital Audio?	92237379	Antenna	0.00	
Antenna > With Digital Audio?	92237380	Antenna	0.00	

### Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Remove & Replace	Antenna & Radio > Antenna, R&R > Convertible	B	0.9	0.0
Remove & Replace	Antenna & Radio > Antenna, R&R > Coupe	B	1.2	0.0

## Radio Antenna Coil Replacement (Article 10988)

Callout Component Name

Preliminary Procedure Remove the rear window panel trim. Refer to Rear Window Panel Trim Replacement .

Preliminary Procedure

Remove the rear window panel trim. Refer to Rear Window Panel Trim Replacement .

1 Radio Antenna Module Coil Bolt Caution: Refer to Fastener Caution . Tighten 10 Nm (89 lb in)

10 Nm (89 lb in)

2 Radio Antenna Coil Procedure Disconnect the electrical connection.

Procedure

Disconnect the electrical connection.