

Component Procedures: Control Assembly

Table of Contents

1. Parts and Labor (itype_189)
2. HVAC - Manual (Article 12792)
3. All Technical Service Bulletins (itype_100)
4. Repair Tips (itype_110)

Component Procedures: Control Assembly

Parts and Labor (itype_189)

Parts

Qualifier	Part #	Name	Price	Note
Dash Control Unit > Without ?	23178061	Dash Control Unit	823.98	
Dash Control Unit > With Hea?	22919383	Dash Control Unit	827.15	

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Remove & Replace	Hvac Case > Dash Control Unit, R&R	B	0.4	0.3

HVAC - Manual (Article 12792)

Non Standards

- Heater and Air Conditioning Control Replacement (12793)

All Technical Service Bulletins (itype_100)

Tsbs

- Infotainment - Blower Speed Appears Frozen on Audio Display (PIC5895B, 2014/02/19)

Repair Tips (itype_110)

Tsbs

- Infotainment - Blower Speed Appears Frozen on Audio Display (PIC5895B, 2014/02/19)