

Component Procedures: Doors, Hood and Trunk

Table of Contents

1. Parts and Labor (itype_189)
2. Trunk, Tailgate, Fuel Doors - Trunk Release Circuit (Article 11939)
3. All Technical Service Bulletins (itype_100)

Component Procedures: Doors, Hood and Trunk

Parts and Labor (itype_189)

Parts


Qualifier	Part #	Name	Price	Note
Trunk	81230F2010	Lock	134.79	
Trunk > Striker	81210F2000	Striker	32.79	
Trunk > Striker	81210F2000	To 2/6/20	32.79	
Front Door	81970F2A00	Lock Cylinder	248.26	
Front Door	81450A4000	Striker	40.27	
Front Door > Lock Actuator	81310F2030	Left	121.76	Includes Door Lock.
Front Door > Lock Actuator	81320F2010	Right	121.76	Includes Door Lock.
Hood	81130F2500	Lock	94.24	
Hood > Release Cable	81190F3500	From Handle	51.89	
Hood > Release Cable > From ?	81190F2600	Korea Built	54.11	
Hood > Release Cable > From ?	81190F3600	Us Built	51.89	
Rear Door	81450A4000	Striker	40.27	
Rear Door > Lock Actuator	81410F2000	Left	303.97	Includes Door Lock.
Rear Door > Lock Actuator	81420F2000	Right	289.48	Includes Door Lock.

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Remove & Replace	Front Door > Lock Actuator, R&R > One Side	B	0.8	0.0
Remove & Replace	Front Door > Lock Cylinder, R&R	B	1.7	0.0
Remove & Replace	Front Door > Lock Switch, R&R > One Side	B	0.5	0.0
Remove & Replace	Front Door > Striker, R&R > Each	C	0.3	0.0
Remove & Replace	Hood > Lock, R&R	B	0.3	0.0
Remove & Replace	Hood > Release Cable, R&R > Front	B	0.3	0.0
Remove & Replace	Hood > Release Cable, R&R > Rear	B	0.7	0.0
Remove & Replace	Rear Door > Lock Actuator, R&R > One Side	B	0.9	0.0
Remove & Replace	Rear Door > Lock, R&R > One Side	B	0.9	0.0
Remove & Replace	Rear Door > Striker, R&R > Each	C	0.3	0.0
Remove & Replace	Trunk > Lock, R&R	B	0.4	0.0
Remove & Replace	Trunk > Release Switch, R&R	B	0.3	0.0
Remove & Replace	Trunk > Striker, R&R	C	0.4	0.0

Trunk, Tailgate, Fuel Doors - Trunk Release Circuit (Article 11939)

Trunk, Tailgate , Fuel Door s - Trunk Release Circuit



All Technical Service Bulletins (itype_100)

Tsbs

- DOOR TRIM PANEL INSPECTION AND SERVICE GUIDE (23-BD-005H, 2023/03/13)