

# **Component Procedures: Cellular Phone**

## **Table of Contents**

1. All New Technical Service Bulletins (itype\_432)
2. All Technical Service Bulletins (itype\_100)
3. Software Update Bulletins (itype\_434)
4. Service Campaigns (itype\_108)

## **Component Procedures: Cellular Phone**

### **All New Technical Service Bulletins (itype\_432)**

Tsbs

- AVN PINHOLE RESET FOR BLUELINK SERVICES (SERVICE CAMPAIGN 9C1) (25-01-024H-1, 2025/05/12)

### **All Technical Service Bulletins (itype\_100)**

Tsbs

- AVN PINHOLE RESET FOR BLUELINK SERVICES (SERVICE CAMPAIGN 9C1) (25-01-024H-1, 2025/05/12)
- BLUELINK, MULTIMEDIA AND NAVIGATION UPDATE FOR 3G SUNSET (22-GI-008H, 2022/12/14)
- HYUNDAI OVER-THE-AIR (OTA) SOFTWARE UPDATE INTRODUCTION AND CUSTOMER COMMUNICATION INFORMATION (23-GI-012H, 2023/12/19)

### **Software Update Bulletins (itype\_434)**

Tsbs

- HYUNDAI OVER-THE-AIR (OTA) SOFTWARE UPDATE INTRODUCTION AND CUSTOMER COMMUNICATION INFORMATION (23-GI-012H, 2023/12/19)

### **Service Campaigns (itype\_108)**

Tsbs

- AVN PINHOLE RESET FOR BLUELINK SERVICES (SERVICE CAMPAIGN 9C1) (25-01-024H-1, 2025/05/12)