

# Component Procedures: Transmission Control Systems

## Table of Contents

1. All Technical Service Bulletins (itype\_100)
2. Customer Interest Bulletins (itype\_109)
3. No shift/Incorrect gear engagement (itype\_154)
4. Noise (itype\_156)
5. New / Updated Parts (itype\_117)

# **Component Procedures: Transmission Control Systems**

## **All Technical Service Bulletins (itype\_100)**

Tsbs

- A/T - Buzz/Whining in Reverse When Cold (21-08-99, 1999/04/30)
- TCM - MIL ON/DTC P1763 Set (21-04-00, 2000/06/30)

## **Customer Interest Bulletins (itype\_109)**

Tsbs

- A/T - Buzz/Whining in Reverse When Cold (21-08-99, 1999/04/30)
- TCM - MIL ON/DTC P1763 Set (21-04-00, 2000/06/30)

## **No shift/Incorrect gear engagement (itype\_154)**

Tsbs

- TCM - MIL ON/DTC P1763 Set (21-04-00, 2000/06/30)

## **Noise (itype\_156)**

Tsbs

- A/T - Buzz/Whining in Reverse When Cold (21-08-99, 1999/04/30)

## **New / Updated Parts (itype\_117)**

Tsbs

- A/T - Buzz/Whining in Reverse When Cold (21-08-99, 1999/04/30)