

Component Procedures: Refrigerant Pressure Sensor / Switch

Table of Contents

1. Parts and Labor (itype_189)
2. Pressure, Vacuum and Temperature (itype_29)
3. All Technical Service Bulletins (itype_100)
4. Customer Interest Bulletins (itype_109)
5. Poor performance (itype_162)
6. New / Updated Parts (itype_117)

Component Procedures: Refrigerant Pressure Sensor / Switch

Parts and Labor (itype_189)

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Replace	Clutch Cycling Switch	B	0.4	0.2

Pressure, Vacuum and Temperature (itype_29)

Low Psi Control opens <
20.5 psi
- resets >
38 psi
High Psi Control switch - opens <
450-490 psi
- resets <
270-330 psi
=
discharge line
mounted switch

All Technical Service Bulletins (itype_100)

Tsbs
- A/C Evaporator - Freeze Up (24-13-99, 1999/07/02)

Customer Interest Bulletins (itype_109)

Tsbs
- A/C Evaporator - Freeze Up (24-13-99, 1999/07/02)

Poor performance (itype_162)

Tsbs
- A/C Evaporator - Freeze Up (24-13-99, 1999/07/02)

New / Updated Parts (itype_117)

Tsbs
- A/C Evaporator - Freeze Up (24-13-99, 1999/07/02)