

Component Procedures: Ball Joint

Table of Contents

1. Parts and Labor (itype_189)
2. All Technical Service Bulletins (itype_100)
3. Customer Interest Bulletins (itype_109)
4. Bouncing (itype_124)
5. Vibration (itype_176)
6. New / Updated Parts (itype_117)

Component Procedures: Ball Joint

Parts and Labor (itype_189)

Parts

Qualifier	Part #	Name	Price	Note
Front Suspension > Coil Spri?	83500202AB	3 - Ball Joints	398.00	

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Replace	Front Suspension > Lower Ball Joint > One Side	B	1.8	0.9
Replace	Front Suspension > Lower Ball Joint > One Sid?	B	0.5	0.0
Replace	Front Suspension > Upper Ball Joints > One Si?	B	1.8	0.9
Replace	Front Suspension > Upper Ball Joints > One Si?	B	0.5	0.0

All Technical Service Bulletins (itype_100)

Tsbs

- Front End Alignment - Adjustable/Offset Ball Joints (02-12-99, 1999/08/20)
- Steering/Suspension - Vibration/Shimmy Above 50 MPH (19-002-12, 2012/07/12)

Customer Interest Bulletins (itype_109)

Tsbs

- Steering/Suspension - Vibration/Shimmy Above 50 MPH (19-002-12, 2012/07/12)

Bouncing (itype_124)

Tsbs

- Steering/Suspension - Vibration/Shimmy Above 50 MPH (19-002-12, 2012/07/12)

Vibration (itype_176)

Tsbs

- Steering/Suspension - Vibration/Shimmy Above 50 MPH (19-002-12, 2012/07/12)

New / Updated Parts (itype_117)

Tsbs

- Front End Alignment - Adjustable/Offset Ball Joints (02-12-99, 1999/08/20)