

Component Procedures: Shift Boot

Table of Contents

1. Parts and Labor (itype_189)

Component Procedures: Shift Boot

Parts and Labor (itype_189)

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Replace	Aisin AX5 > Shift Boot	C	0.3	0.0
Replace	Aisin AX15 > Shift Boot	C	0.3	0.0