

Component Procedures: Antenna Cable

Table of Contents

1. Parts and Labor (itype_189)
2. Components (itype_32)
3. Antenna Feeder (Article 1413680)

Component Procedures: Antenna Cable

Parts and Labor (itype_189)

Parts

Qualifier	Part #	Name	Price	Note
Antenna Cable > 4 Door > Fro?	BP4K66940B	Antenna Cable	55.80	
Antenna Cable > 4 Door > Fro?	B33D66940B	Antenna Cable	82.60	
Antenna Cable > 4 Door > Fro?	BAP666940A	Antenna Cable	144.15	
Antenna Cable > 4 Door > Cen?	BN8V66940B	Antenna Cable	55.82	
Antenna Cable > 4 Door > Cen?	BAP166940A	Antenna Cable	145.30	
Antenna Cable > 4 Door > Cen?	BN8W66940B	Antenna Cable	56.35	
Antenna Cable > 4 Door > Cen?	BAP266940A	Antenna Cable	151.53	
Antenna Cable > 4 Door > Rea?	BN9A66940	Antenna Cable	64.40	
Antenna Cable > 4 Door > Rea?	BAP366940	Antenna Cable	118.08	
Antenna Cable > 5 Door > Fro?	BP4K66940B	Antenna Cable	55.80	
Antenna Cable > 5 Door > Fro?	B33D66940B	Antenna Cable	82.60	
Antenna Cable > 5 Door > Fro?	BAP666940A	Antenna Cable	144.15	
Antenna Cable > 5 Door > Cen?	BP4L66940B	Antenna Cable	63.28	
Antenna Cable > 5 Door > Cen?	B32H66940C	Antenna Cable	79.28	
Antenna Cable > 5 Door > Cen?	BAP866940A	Antenna Cable	151.13	
Antenna Cable > 5 Door > Cen?	BP4M66940D	Antenna Cable	66.80	
Antenna Cable > 5 Door > Cen?	BAR266940	Antenna Cable	68.03	
Antenna Cable > 5 Door > Cen?	BAP966940A	Antenna Cable	0.00	
Antenna Cable > 5 Door > Rea?	BP4N66940A	Antenna Cable	129.02	
Antenna Cable > 5 Door > Rea?	B32L66940A	Antenna Cable	96.76	
Antenna Cable > 5 Door > Rea?	BAR166940A	Antenna Cable	131.78	


Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Replace	Antenna Assy, R&R	B	2.2	1.5
Replace	Front	B	0.9	0.6
Replace	Rear	B	2.2	1.5

Components (itype_32)

ANTENNA FEEDER LOCATION

id092000801800



c3u0920w109

1	Front antenna feeder
2	Rear antenna feeder No.1

3	Rear antenna feeder No.2
---	--------------------------

Antenna Feeder (Article 1413680)

Non Standards

- Front (1413681)
- Rear (1413682)