

Component Procedures: Evaporator Core

Table of Contents

1. Parts and Labor (itype_189)
2. All Technical Service Bulletins (itype_100)
3. Customer Interest Bulletins (itype_109)
4. Poor performance (itype_162)

Component Procedures: Evaporator Core

Parts and Labor (itype_189)

Parts

Qualifier	Part #	Name	Price	Note
Evaporator Core	CCY361J1Z	Evaporator Core	496.53	

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Replace	Evaporator Core	B	7.5	0.0

All Technical Service Bulletins (itype_100)

Tsbs

- A/C - Stops Cooling After Long Drive When Hot/Humid (0701109, 2009/09/18)

Customer Interest Bulletins (itype_109)

Tsbs

- A/C - Stops Cooling After Long Drive When Hot/Humid (0701109, 2009/09/18)

Poor performance (itype_162)

Tsbs

- A/C - Stops Cooling After Long Drive When Hot/Humid (0701109, 2009/09/18)