

Component Procedures: Tune-up and Engine Performance Checks

Table of Contents

1. Parts and Labor (itype_189)
2. Specifications Quick Reference (itype_439)
3. All New Technical Service Bulletins (itype_432)
4. All Technical Service Bulletins (itype_100)
5. Repair Tips (itype_110)

Component Procedures: Tune-up and Engine Performance Checks

Parts and Labor (itype_189)

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Test	Ignition System > Compression, Test	B	3.1	0.0

Specifications Quick Reference (itype_439)

Quick Specifications

- item

All New Technical Service Bulletins (itype_432)

Tsbs

- Fluid in Spark Plug Tubes, Coolant and/or Oil Leak, Malfunction Indicator Lamp (MIL) Illuminated (21-NA-147, 2025/07/25)

All Technical Service Bulletins (itype_100)

Tsbs

- SES Light with Fuel Trim and or Oxygen Sensor Codes (PIP4925B, 2018/12/03)
- Fluid in Spark Plug Tubes, Coolant and/or Oil Leak, Malfunction Indicator Lamp (MIL) Illuminated (21-NA-147, 2025/07/25)
- Engine Controls - Single Cylinder Misfire Diagnostics (PIP5062C, 2014/05/02)

Repair Tips (itype_110)

Tsbs

- Engine Controls - Single Cylinder Misfire Diagnostics (PIP5062C, 2014/05/02)