

Component Procedures: Fluids

Table of Contents

1. Parts and Labor (itype_189)
2. All New Technical Service Bulletins (itype_432)
3. All Technical Service Bulletins (itype_100)
4. Repair Tips (itype_110)
5. Leaks (itype_149)
6. Out of specification (itype_158)
7. Fluids, Chemicals and Additives (itype_112)
8. OEM Policies and Procedures (itype_120)

Component Procedures: Fluids

Parts and Labor (itype_189)

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Service	Periodical Maintenance > Lube & Filter, Servi?	C	0.7	0.0
Service	Periodical Maintenance > Lube & Filter, Servi?		0.1	
Change	Automatic Transmission > Trans Fluid, Change	C	1.0	0.8
Change	Automatic Transmission > Trans Fluid, Change ?		0.1	
Change	Differential > Fluid, Change	C	0.5	0.0
Change	Manual Transmission > Trans Fluid, Change	C	0.5	0.0

All New Technical Service Bulletins (itype_432)

Tsbs

- Information Regarding the Differences Between Fluid Leakage and Seepage (15-00-89-004H, 2026/02/04)
- Fuel and Oil Additives - Facts and Myths - Maximizing Gasoline Fuel Economy (05-00-89-072H, 2026/05/05)
- Information on Refrigerant (R1234yf) for A/C Service (12-01-37-001G, 2024/07/24)
- Information on Engine Oil Consumption Guidelines (01-06-01-011S, 2025/07/28)

All Technical Service Bulletins (itype_100)

Tsbs

- Information on 6L50 (MYB), 6L80 (MYC) and 6L90 (MYD) Automatic Transmission Oil Filter and Seal Kit Part Number (23-NA-224, 2023/12/18)
- Information Regarding the Differences Between Fluid Leakage and Seepage (15-00-89-004H, 2026/02/04)
- Engine - dexos 1(R) and dexos 2(R) Oil Specs/Information (11-00-90-001B, 2013/05/21)
- PIP5257D: Cooling System Contaminated With Engine Oil (PIP5257D, 2020/04/17)
- Fuel and Oil Additives - Facts and Myths - Maximizing Gasoline Fuel Economy (05-00-89-072H, 2026/05/05)
- Information on Refrigerant (R1234yf) for A/C Service (12-01-37-001G, 2024/07/24)
- Engine Oil Dye May be Mistaken for Contamination on Low Mileage Engines (PI0275B, 2012/02/17)
- Engine - Oil Leak Prevention After Oil/Filter Change (15-00-90-001, 2015/03/06)
- Questions Regarding The Use Of High Performance / High Temperature Brake Fluid During Track Use (PIC6162D, 2021/01/19)
- Information on Engine Oil Consumption Guidelines (01-06-01-011S, 2025/07/28)
- Power Steering Noise or Fluid Leak from Power Steering Pump, Gear or High Pressure Hose During Extreme Low Temperature Operation (Replace Power Steering Fluid) (12-02-32-002B, 2020/06/05)
- Information for Repairing Engine Front Cover Oil Leak, Sealing Surface Preparation and Applying RTV Sealant (12-06-01-003D, 2022/05/02)

Repair Tips (itype_110)

Tsbs

- Engine - dexos 1(R) and dexos 2(R) Oil Specs/Information (11-00-90-001B, 2013/05/21)
- Engine - Oil Leak Prevention After Oil/Filter Change (15-00-90-001, 2015/03/06)

Leaks (itype_149)

Tsbs

- Power Steering Noise or Fluid Leak from Power Steering Pump, Gear or High Pressure Hose During Extreme Low Temperature Operation (Replace Power Steering Fluid) (12-02-32-002B, 2020/06/05)
- Information for Repairing Engine Front Cover Oil Leak, Sealing Surface Preparation and Applying RTV Sealant (12-06-01-003D, 2022/05/02)

Out of specification (itype_158)

Tsbs

- PIP5257D: Cooling System Contaminated With Engine Oil (PIP5257D, 2020/04/17)

Fluids, Chemicals and Additives (itype_112)

Tsbs

- Fuel and Oil Additives - Facts and Myths - Maximizing Gasoline Fuel Economy (05-00-89-072H, 2026/05/05)

- Information on Refrigerant (R1234yf) for A/C Service (12-01-37-001G, 2024/07/24)

OEM Policies and Procedures (itype_120)

Tsbs

- Information Regarding the Differences Between Fluid Leakage and Seepage (15-00-89-004H, 2026/02/04)

- Information on Refrigerant (R1234yf) for A/C Service (12-01-37-001G, 2024/07/24)

- Engine Oil Dye May be Mistaken for Contamination on Low Mileage Engines (PI0275B, 2012/02/17)

- Questions Regarding The Use Of High Performance / High Temperature Brake Fluid During Track Use (PIC6162D, 2021/01/19)

- Information on Engine Oil Consumption Guidelines (01-06-01-011S, 2025/07/28)