

Component Procedures: Relays and Modules - Brakes and Traction Control

Table of Contents

1. All New Technical Service Bulletins (itype_432)
2. All Technical Service Bulletins (itype_100)

Component Procedures: Relays and Modules - Brakes and Traction Control

All New Technical Service Bulletins (itype_432)

Tsbs

- Multiple U-code Diagnostic Information – With one having symptom Byte 71 (PIT5569C, 2024/09/06)

All Technical Service Bulletins (itype_100)

Tsbs

- Multiple U-code Diagnostic Information – With one having symptom Byte 71 (PIT5569C, 2024/09/06)