

Component Procedures: Suspension Strut / Shock Absorber

Table of Contents

1. Parts and Labor (itype_189)
2. Rear Suspension (Article 13575)
3. Front Suspension (Article 13547)
4. All New Technical Service Bulletins (itype_432)
5. All Technical Service Bulletins (itype_100)
6. Suspension General Diagnosis (Article 13608)
7. OEM Policies and Procedures (itype_120)

Component Procedures: Suspension Strut / Shock Absorber

Parts and Labor (itype_189)

Parts

Qualifier	Part #	Name	Price	Note
Front Suspension > Strut > R?	22922597	3 - Strut	295.99	
Front Suspension > Strut > R?	22922601	3 - Strut	0.00	
Front Suspension > Strut > R?	22952189	3 - Strut	1000.12	
Front Suspension > Strut > R?	22737717	3 - Strut	379.26	
Front Suspension > Strut > L?	22922596	3 - Strut	293.86	
Front Suspension > Strut > L?	22922600	3 - Strut	0.00	
Front Suspension > Strut > L?	22952188	3 - Strut	1233.92	
Front Suspension > Strut > L?	22737716	3 - Strut	386.70	
Rear Suspension > Shock Abso?	22809066	7 - Shock Absorber	271.59	

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Remove & Replace	Front Suspension > Suspension Components > St?	B	1.4	1.1
Remove & Replace	Front Suspension > Suspension Components > St?	B	2.6	2.0
Remove & Replace	Rear Suspension > Suspension Components > Str?	B	1.2	0.0
Remove & Replace	Rear Suspension > Suspension Components > Str?	B	2.4	0.0

Rear Suspension (Article 13575)

Non Standards

- Shock Absorber, Shock Absorber Component, or Spring Replacement (W/FE5) (13580)
- Shock Absorber, Shock Absorber Component, or Spring Replacement (WO/FE5) (13582)
- Shock Absorber Replacement (W/FE5) (13576)
- Shock Absorber Replacement (WO/FE5) (13577)

Front Suspension (Article 13547)

Non Standards

- Strut Assembly Removal and Installation (W/FE5) (13548)
- Strut Assembly Removal and Installation (W/OFE5) (13549)
- Strut, Strut Component, or Spring Replacement (13552)

All New Technical Service Bulletins (itype_432)

Tsbs

- Information on Diagnosis and Replacement of Shock Absorber and Strut Due to Fluid Leak (05-03-08-002J, 2024/08/22)

All Technical Service Bulletins (itype_100)

Tsbs

- Information on Diagnosis and Replacement of Shock Absorber and Strut Due to Fluid Leak (05-03-08-002J, 2024/08/22)

Suspension General Diagnosis (Article 13608)

Non Standards

- Suspension Strut and Shock Absorber Testing - On Vehicle (13609)

OEM Policies and Procedures (itype_120)

Tsbs

- Information on Diagnosis and Replacement of Shock Absorber and Strut Due to Fluid Leak (05-03-08-002J, 2024/08/22)