

Component Procedures: Relays and Modules - Computers and Control Systems

Table of Contents

1. All New Technical Service Bulletins (itype_432)
2. All Technical Service Bulletins (itype_100)
3. Software Update Bulletins (itype_434)
4. OEM Policies and Procedures (itype_120)
5. Service Campaigns (itype_108)

Component Procedures: Relays and Modules - Computers and Control Systems

All New Technical Service Bulletins (itype_432)

Tsbs

- IBU/BCM ANTI-THEFT SOFTWARE UPGRADE AND DECAL APPLICATION (SERVICE CAMPAIGN 993) (24-01-009H-1, 2024/05/09)
- ECU SOFTWARE UPDATE – OBD-II FUEL SYSTEM READINESS MONITOR DIAGNOSIS (SERVICE CAMPAIGN 968) (25-01-054H, 2025/08/19)

All Technical Service Bulletins (itype_100)

Tsbs

- ECM AND PCM VIN WRITING DURING CONTROL MODULE REPLACEMENT (19-FL-003H, 2019/04/16)
- IAU/IBU/BLE LEARNING AFTER PARTS REPLACEMENT (22-BE-004H, 2022/07/08)
- ECM SOFTWARE UPDATE – MISFIRE DTC LOGIC (SERVICE CAMPAIGN T3W) (20-01-008H, 2020/02/14)
- IDLE STOP & GO SYSTEM OPERATION, DIAGNOSTIC AND BATTERY SENSOR RECALIBRATION PROCEDURE (20-FL-004H, 2020/05/29)
- IBU/BCM ANTI-THEFT SOFTWARE UPGRADE AND DECAL APPLICATION (SERVICE CAMPAIGN 993) (24-01-009H-1, 2024/05/09)
- ECU SOFTWARE UPDATE – OBD-II FUEL SYSTEM READINESS MONITOR DIAGNOSIS (SERVICE CAMPAIGN 968) (25-01-054H, 2025/08/19)
- ENGINE MONITORING LOGIC (SERVICE CAMPAIGN 974) (22-01-043H, 2022/05/09)

Software Update Bulletins (itype_434)

Tsbs

- IDLE STOP & GO SYSTEM OPERATION, DIAGNOSTIC AND BATTERY SENSOR RECALIBRATION PROCEDURE (20-FL-004H, 2020/05/29)

OEM Policies and Procedures (itype_120)

Tsbs

- ECM AND PCM VIN WRITING DURING CONTROL MODULE REPLACEMENT (19-FL-003H, 2019/04/16)
- IAU/IBU/BLE LEARNING AFTER PARTS REPLACEMENT (22-BE-004H, 2022/07/08)

Service Campaigns (itype_108)

Tsbs

- ECM SOFTWARE UPDATE – MISFIRE DTC LOGIC (SERVICE CAMPAIGN T3W) (20-01-008H, 2020/02/14)
- IBU/BCM ANTI-THEFT SOFTWARE UPGRADE AND DECAL APPLICATION (SERVICE CAMPAIGN 993) (24-01-009H-1, 2024/05/09)
- ECU SOFTWARE UPDATE – OBD-II FUEL SYSTEM READINESS MONITOR DIAGNOSIS (SERVICE CAMPAIGN 968) (25-01-054H, 2025/08/19)
- ENGINE MONITORING LOGIC (SERVICE CAMPAIGN 974) (22-01-043H, 2022/05/09)