

Component Procedures: Blower Motor

Table of Contents

1. Parts and Labor (itype_189)
2. Electrical (OE) (itype_21)
3. HVAC Control System (Article 1409924)
4. Removal and Replacement (itype_401)
5. All Technical Service Bulletins (itype_100)
6. Repair Tips (itype_110)
7. Blower Motor Inspection (Article 1414733)

Component Procedures: Blower Motor

Parts and Labor (itype_189)

Parts

Qualifier	Part #	Name	Price	Note
Blower Motor	BP4K61B10	Blower Motor	210.73	

Labor

Operation	Qualifier Path	Skill	Std Hrs	Wty Hrs
Replace	Blower Motor	B	4.2	0.0
Replace	Blower Motor > NOTE > With Navigation, Add	B	0.3	0.0

Electrical (OE) (itype_21)

For information regarding diagrams for this component, please refer to Heating and Air Conditioning Diagrams.


See: Heating and Air Conditioning > Electrical

HVAC Control System (Article 1409924)


Non Standards

- Full-Auto Air Conditioner (1409931)
- Manual Air Conditioner (1409932)


Removal and Replacement (itype_401)




am3uuw000064




am3uuw000064




am3uuw000064




am3uuw000064




am3uuw000064




am3uuw000065



am3uuw000065





am3uuw000065




am3uuw000065


**BLOWER MOTOR
CONNECTOR**




am3zzw000084




am3uuw000065




am3uuw000065




am3zzw000085




am3uuw000065




am3uuw000065




am3uuw000065




am3uuw000063




am3uuw000064




am3uuw000064




am3uuw0000064




am3uuw0000064



am3zzw0000077



b3a0740w003



am3uuw000064

All Technical Service Bulletins (itype_100)

Tsbs


- A/C - Poor Blower Motor Performance (MTIP-08-03-1, 2008/03/01)

Repair Tips (itype_110)

Tsbs

- A/C - Poor Blower Motor Performance (MTIP-08-03-1, 2008/03/01)

Blower Motor Inspection (Article 1414733)



am3uuw000062