

Component Procedures: Front Door Window Glass Weatherstrip

Table of Contents

1. Front Side Door Window Inner Sealing Strip Replacement (Article 10263)
2. Front Side Door Window Belt Reveal Molding Replacement (Article 10262)
3. All Technical Service Bulletins (itype_100)
4. Repair Tips (itype_110)

Component Procedures: Front Door Window Glass Weatherstrip

Front Side Door Window Inner Sealing Strip Replacement (Article 10263)

Callout Component Name

Preliminary Procedure Remove the interior trim panel . Refer to Front Side Door Trim Panel Replacement .

Preliminary Procedure

Remove the interior trim panel . Refer to Front Side Door Trim Panel Replacement .

1 Front Side Door Window Inner Sealing Strip Retainers (Qty: 3)

2 Front Side Door Window Inner Sealing Strip Procedure Inspect the door for proper operation before installing the door trim panel. Tip: Pull up and away from inner panel to remove from the door.

Procedure

Inspect the door for proper operation before installing the door trim panel.

Front Side Door Window Belt Reveal Molding Replacement (Article 10262)

Callout Component Name

Preliminary Procedures Remove the outside rearview mirror . Refer to Outside Rearview Mirror Replacement

Preliminary Procedures

Remove the outside rearview mirror . Refer to Outside Rearview Mirror Replacement

1 Front Side Door Window Belt Reveal Molding Fastener Caution: Refer to Fastener Caution . Procedure Remove the three retaining screws and the fin trim to remove the sealing strip . Tighten 1 Nm (9 lb in)

Procedure

Remove the three retaining screws and the fin trim to remove the sealing strip .

1 Nm (9 lb in)

2 Front Side Door Belt Reveal Molding Procedure Inspect the door for proper operation before installing the door trim panel . Tip: Pull the outer sealing strip up and away from the upper door flange.

Inspect the door for proper operation before installing the door trim panel .

All Technical Service Bulletins (itype_100)

Tsbs

- Body - Front/Rear Side Door Windows Bind/Noisy/Move Slowly (PI0018B, 2013/11/08)

Repair Tips (itype_110)

Tsbs

- Body - Front/Rear Side Door Windows Bind/Noisy/Move Slowly (PI0018B, 2013/11/08)